



Dimensions (mm)													
D1 (D10)	D2 (K7)	D6	D7	D8 (+/-0,2)	A	B1 (+0/0,3)	B2 (-0,1)	B3	C	H1	H2	M1	M2
25	35	15	M12	M10	165	45	35	40	22	40	85	125	65
30	40	15	M12	M10	165	45	35	40	22	40	85	125	65
35	45	15	M12	M10	180	50	40	45	25	50	100	140	75
40	50	15	M12	M10	180	50	40	45	25	50	100	140	75
45	55	19	M16	M12	210	55	45	50	30	60	120	160	90
50	60	19	M16	M12	210	55	45	50	30	60	120	160	90
55	65	19	M16	M12	225	60	50	55	35	70	140	175	100
60	70	19	M16	M12	225	60	50	55	35	70	140	175	100
65*	80	24	M20	M16	270	65	53	60	40	80	160	210	120
70	85	24	M20	M16	270	65	53	60	40	80	160	210	120
75*	90	24	M20	M16	290	75	63	70	45	90	180	230	130
80	95	24	M20	M16	290	75	63	70	45	90	180	230	130
90	105	28	M24	M20	330	85	73	80	50	100	200	265	150
100	115	28	M24	M20	355	95	81	90	55	110	220	290	170
110	125	28	M24	M20	355	95	81	90	55	110	220	290	170
120*	140	35	M30	M24	420	110	94	100	60	130	260	340	200
125	145	28	M24	M20	420	110	94	100	60	110	220	290	170
130*	150	35	M30	M24	420	110	94	100	60	130	260	340	200
140	160	35	M30	M24	440	125	105	120	65	150	300	360	220
150*	170	35	M30	M24	440	125	105	120	65	150	300	360	220

* = If possible, please avoid this size.